

AD-A074 025

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON
NATIONAL DAM SAFETY PROGRAM. LAKE TOPANEMUS DAM (NJ-00219), RAR--ETC(U)
AUG 79 A 6 POSCH


F/G 13/2
RAR--ETC(U)

DACW61-79-C-0011

NL

UNCLASSIFIED

1 OF 1
AD
A074025



Approved for public release;
distribution unlimited

RARITAN RIVER BASIN
McGELLAIRDS BROOK, MONMOUTH COUNTY
NEW JERSEY

LAKE TOPANEMUS DAM
NJ 00219



PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



ORIGINAL CONTAINS COLOR PLATES: ALL
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

DDC FILE COPY

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

August, 1979 09 19 024

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00219	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake Topanemus Monmouth County, N.J.	5. TYPE OF REPORT & PERIOD COVERED 9 FINAL rept.	
7. AUTHOR(s) 10 Posch, Anthony G. / Posch	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Harris -ECI 453 Amboy Ave. Woodbridge, N.J. 03301	8. CONTRACT OR GRANT NUMBER(s) 15 DACW61-79-C-0011	
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 12 90p.	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	12. REPORT DATE 11 August 1979	
	13. NUMBER OF PAGES 60	
	15. SECURITY CLASS. (of this report) Unclassified	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Block 16) 6 National Dam Safety Program. Lake Topanemus Dam (NJ-00219), Raritan River Basin, McGellaids Brook, Monmouth County, New Jersey. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Lake Topanemus Dam, N.J. Structural Analysis Spillway Visual Inspection Slope National Dam Inspection Act. report Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

410 891

J04B

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**



IN REPLY REFER TO

NAPEN-D

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

12 SEP 1979

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Lake Topanemus Dam in Monmouth County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Topanemus Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 13 percent of the Spillway Design Flood--SDF - would overtop the dam. (The SDF, in this instance, is one half of the Probable Maximum Flood.) The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the determination that dam failure resulting from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure.

To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operations plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

NAPEN-D

Honorable Brendan T. Byrne

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1980.

c. The ownership of the dam should be established within thirty days from the date of approval of this report.

d. The following remedial actions should be completed within six months from the date of approval of this report.

(1) Replace embankment material that has been lost from the downstream face, particularly adjacent to the abutments of the bridge/spillway.

(2) Concrete slope protection should be provided under road drain outfalls, to reduce erosion.

(3) Restore the areas of eroded and spalled concrete and repair cracks to arrest further deterioration.

(4) Fabricate new operating keys for the low-level outlet valves. Clear the key shafts of debris and provide a lockable device for the shaft caps.

e. Remove trees and vegetation from the downstream embankment face and seed with grass within 12 months from the date of approval of this report.

f. The following remedial actions should be completed within one to three years from the date of approval of this report:

(1) A program should be developed to monitor the seepage through and under the dam. Depending on the information provided, the need for corrective measures can be considered and, if necessary, undertaken.

(2) Further plans and drawings of the dam should be made and annotated to form a coherent as-built set.

(3) A program of annual inspection and maintenance should be initiated. This should include lowering the lake and updating the operation and maintenance log.

NAPEN-D

Honorable Brendan T. Byrne


(4) Develop schemes for increasing the low-level outlet capacity.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman James J. Howard of the Third District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,


JOEL T. CALLAHAN
Lieutenant Colonel, Corps of Engineers
Acting District Engineer

1 Incl
As stated

Copies furnished:

Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or special
A	

LAKE TOPANEMUS DAM (NJ00219)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 30 April, 24 May and 1 June 1979 by Frederic R. Harris, Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Lake Topanemus Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 13 percent of the Spillway Design Flood--SDF - would overtop the dam. (The SDF, in this instance, is one half of the Probable Maximum Flood.) The decision to consider the spillway "inadequate" instead of "seriously inadequate" is based on the determination that dam failure resulting from overtopping would not significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure.

To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operations plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around the clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1980.

c. The ownership of the dam should be established within thirty days from the date of approval of this report.

d. The following remedial actions should be completed within six months from the date of approval of this report.

(1) Replace embankment material that has been lost from the downstream face, particularly adjacent to the abutments of the bridge/spillway.

(2) Concrete slope protection should be provided under road drain outfalls, to reduce erosion.

(3) Restore the areas of eroded and spalled concrete and repair cracks to arrest further deterioration.

(4) Fabricate new operating keys for the low-level outlet valves. Clear the key shafts of debris and provide a lockable device for the shaft caps.

e. Remove trees and vegetation from the downstream embankment face and seed with grass within 12 months from the date of approval of this report.

f. The following remedial actions should be completed within one to three years from the date of approval of this report:

(1) A program should be developed to monitor the seepage through and under the dam. Depending on the information provided, the need for corrective measures can be considered and, if necessary, undertaken.

(2) Further plans and drawings of the dam should be made and annotated to form a coherent as-built set.

(3) A program of annual inspection and maintenance should be initiated. This should include lowering the lake and updating the operation and maintenance log.

(4) Develop schemes for increasing the low-level outlet capacity.

APPROVED:

Joel T. Callahan
JOEL T. CALLAHAN

Lieutenant Colonel, Corps of Engineers
Acting District Engineer

DATE:

11 September 1979

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake Topanemus, I.D. NJ00219
State Located: New Jersey
County Located: Monmouth County
Stream: McGellairds Brook
Date of Inspection: April 30, May 24 and June 1, 1979

Assessment of General Condition

Lake Topanemus Dam is an earth-fill road embankment approximately 350 feet long and 20 feet high, with a concrete spillway. The general condition of Lake Topanemus Dam is fair. There is evidence of seepage from the downstream face of the embankment, and this area is heavily overgrown with brush and trees. Small areas of concrete in the spillway have been eroded and spillway wingwalls show signs of settlement. The low-level outlets are not presently operable. The hazard potential is rated as "high."

The safety of Lake Topanemus Dam is considered questionable in view of its lack of spillway capacity to pass one half the PMF without overtopping the dam. The spillway is capable of passing a flood equal to 6% of the PMF, and is assessed as "inadequate."

At present, the engineering data available is not sufficient to make a definitive statement on the stability of the dam.

The following actions, therefore, are recommended along with a timetable for their completion.


1. Establish ownership of the dam immediately.
2. Perform a chemical analysis of the seepage from the left-hand downstream face immediately, to determine its source.
3. Establish a flood warning system for the downstream communities within three months, especially for the lowland area between Taylor Mills and the Borough of Englishtown.
4. Carry out a more precise hydrologic and hydraulic analysis of the dam within six months, to determine the need and type of mitigating measures necessary. If required, conduct a study of the means of

increasing spillway discharge capacity and develop alternative schemes for construction. This should include the installation of headwater and tailwater gages.

5. Install observation wells or piezometers in the downstream embankment, and log the borings to determine engineering properties of the dam fill and foundation material. This program and a stability analysis based on the findings should be completed within six months.
6. Carry out remedial measures to the dam structure within six months, including replacement of eroded material; repair of eroded, cracked and spalled concrete with epoxy cement; provision of slope protection under road-drain outfalls; restoration of low-level outlets to an operable condition.
7. Remove trees and vegetation from the downstream embankment face and seed with grass within 12 months.

Furthermore, while of a less urgent nature, the following additional action is recommended and should be carried out within a reasonable period of time.

1. A program should be developed to monitor the seepage through and under the dam. Depending on the information provided, the need for corrective measures can be considered and, if necessary, undertaken.
2. Further plans and drawings of the dam should be made and annotated to form a coherent as-built set.
3. A program of annual inspection and maintenance should be initiated. This should include lowering the lake and updating the operation and maintenance log.
4. Develop schemes for increasing the low-level outlet capacity.



Anthony G. Posch, P.E.

AGP/REJ/ak



Lake Topanemus Dam
View of upstream face of the dam.

April 30, 1979

TABLE OF CONTENTS

ASSESSMENT OF GENERAL CONDITION

PREFACE

	<u>Page</u>
SECTION 1 PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	4
SECTION 2 ENGINEERING DATA	7
2.1 Design	7
2.2 Construction	7
2.3 Operation	7
2.4 Evaluation	7
SECTION 3 VISUAL INSPECTION	8
3.1 Findings	8
SECTION 4 OPERATIONAL PROCEDURES	11
4.1 Procedures	11
4.2 Maintenance of Dam	11
4.3 Maintenance of Operating Facilities	11
4.4 Evaluation	11
SECTION 5 HYDRAULIC/HYDROLOGIC	12
5.1 Evaluation of Features	12
SECTION 6 STRUCTURAL STABILITY	14
6.1 Evaluation of Structural Stability	14
SECTION 7 ASSESSMENT/REMEDIAL MEASURES	16
7.1 Dam Assessment	16
7.2 Remedial Measures	17

TABLE OF CONTENTS CONTINUED

PLATES

	<u>No.</u>
VICINITY MAP	1
GEOLOGIC MAP	2
DRAWINGS OF DAM	3-4

APPENDICES

APPENDIX A - CHECK LIST - VISUAL OBSERVATIONS	
CHECK LIST - ENGINEERING, CONSTRUCTION, MAINTENANCE DATA	
APPENDIX B - PHOTOGRAPHS	
APPENDIX C - SUMMARY OF ENGINEERING DATA	
APPENDIX D - HYDROLOGIC COMPUTATIONS	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT

NATIONAL DAM SAFETY PROGRAM

Lake Topanemus Dam, I.D. NJ00219

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act (Public Law 92-367, 1972) provides for the National Inventory and Inspection Program by the U.S. Army Corps of Engineers. This inspection was made in accordance with this authority under Contract C-FPM No. 35 with the State of New Jersey who, in turn is contracted to the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspection of Lake Topanemus Dam was made on April 30, May 24 and June 1, 1979. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the Field Inspection; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

1.2 Description of Project

a. Description of Dam and Appurtenances

Lake Topanemus Dam is an earth-fill embankment, about 20 feet high and 350 feet long, having an unregulated concrete spillway of the broadcrested weir type towards the right side of the dam. The dam forms part of Pond Road, a two-lane paved road which passes over a reinforced concrete bridge at the spillway; the side and wing-walls of the spillway forming the bridge abutments. The bridge is supported at two intermediate points in its length by continuous concrete piers, which subdivide the spillway into three channels, each approximately 9 feet wide. The weir gains further lateral support

from one intermediate counterfort in each channel. The counterforts project above the weir and tie into the bridge deck, forming six separate openings 4 feet wide. The sides of the counterforts and bridge piers which face the flow over the weir are reinforced against erosion by rolled-steel channel sections. The weir crest is 9 inches thick and its distance below the road surface is 2.8 feet. The spillway apron is of concrete construction and steps down in three horizontal stages to the downstream end. The bridge and spillway structure consists of an original part with an extension added in 1927.

The embankment extends approximately 280 feet to the left and 35 feet to the right of the spillway. The upstream face of the left embankment is retained by a 4 feet high timber bulkhead. The downstream face is sloped at 2H:1V. About 50 cubic yards of sandy fill has recently been placed and graded around a hydrant located at the top of the face. Adjacent to the spillway, the downstream embankment is retained on each side by concrete wingwalls, 10 feet long, on spread footings. A jury-rigged timber extension to the left wingwall retains the embankment for a further 10 feet. The top of the embankment is approximately 35 feet wide and in addition to a 25 feet wide road, the embankment carries for its full length overhead power cables on pylons, underground ducts (presumed telephone conduits), a water main and on the upstream side, a traffic barrier. Two 12" diameter road drains discharge onto the downstream face. No evidence was found to indicate the presence of a clay or concrete core.

On the upstream right-hand side of the spillway, there is a small parking area for the use of the local fire department. The area is retained by concrete walls, and a testing pipe extending into the water has been affixed to one wall. A sluice opening exists on the upstream wall and is not now used. It is reported to be the original spillway from Lake Topanemus.

McGellairs Brook turns to the left after passing through the spillway and runs parallel to the embankment toe for several yards before heading west. The remainder of the embankment toe terminates at a small drainage channel which discharges into the brook. The dam is thought to be founded on Red Bank and Tinton Falls sands which have a high silt content.

There are two low-level outlets to the dam, both of which are cast iron valves located in the central section of the spillway wall on the upstream face. The valves are operated manually from the bridge by means of a long removable valve key. The larger, 18 inch diameter, gate valve is located at the bottom of the vertical weir with its invert approximately 12 feet below the road level. The other is a 12 inch diameter gate valve at 7 feet below the road level. Both valve key shafts project above the water

surface and have bolted caps. The outlets are not presently operable.

b. Location

Lake Topanemus Dam is located in the Township of Freehold, Monmouth County, New Jersey. It is accessible by means of Pond Road which passes across the dam.

c. Size and Hazard Classification

Lake Topanemus Dam has a structural height of 20 feet and a reservoir storage of 141 acre-feet. Since its storage is less than 1,000 acre-feet and its height is less than 40 feet, it is classified in the dam size category as being "small." A hazard potential classification of "high" has been assigned to the dam on the basis that failure would result in excessive damage to the road and services across the dam and to downstream property, including Route 9. Because the road across the dam is heavily traveled, and because Lake Topanemus is used for recreational purposes, the possibility exists of the loss of more than a few lives in the event of dam failure. There are few inhabitable buildings within one mile downstream of the dam. Old Tennent, within 3 miles of the dam has more than 20 residential houses.

d. Ownership

The ownership of Lake Topanemus Dam could not be established after a thorough search. Enquiries were addressed to Engineers and Clerks for the Township of Freehold, the Borough of Freehold, Monmouth County and the NJDEP, none of whom were able to locate the title.

Pond Road, which crosses the dam, is maintained by the Township of Freehold as is the water main.

Township of Freehold

Engineer: Mr. Dickerson (201) 462-7900

Borough of Freehold

Engineer: Mr. Patel (201) 462-4200
51 W. Main Street
Freehold, NJ 07728

e. Purpose of Dam

Lake Topanemus is a Borough Recreational Facility for small non-powered boats and for fishing. The present purpose of the dam is

solely to retain the lake. Originally a commercial ice house operated from the lake.

f. Design and Construction History

No drawings or computations pertaining to the original construction could be found. However, it was reported by a local inhabitant that a one-lane road and the spillway were built before the turn of the century. Prior to that, the only outlet from the lake was a surface-level culvert on the right of the embankment. The date of construction of the original dam is not known.

A plan dated 1920, shows construction details for widening the road and spillway by 13 feet. The Assistant Engineer for Monmouth County reported that Pond Road was not expanded to its present two-lane form until 1927. The stub wingwalls were also built then.

Installation of the cable conduits took place after 1927 as the bridge piers and abutments have been broken out to allow them to pass over the spillway. The watermain was installed by the Township in 1978. The lake was drained down in 1961 following a case of drowning. It was drained through the low-level outlets which have not since been operated. It is not recorded how long the duration of drawdown was.

g. Normal Operating Procedures

The normal discharge from the lake is over the unregulated spillway and it is allowed to balance naturally with inflow to the lake. Two low-level outlets were not operable at the time of inspection. The lake is not lowered on a regular basis.

1.3 Pertinent Data

- | | |
|---|--------------------------------|
| a. <u>Drainage Area</u> | 1.6 square miles |
| b. <u>Discharge at Dam Site</u> | |
| Maximum known flood at dam site: | None over road. |
| Ungated spillway capacity at elevation of top of dam: | 176 cfs
(el. 120' assumed) |
| Total spillway capacity at maximum pool elevation: | 245 cfs
(el. 122.1 assumed) |
| c. <u>Elevation (Feet Above MSL)</u> | |
| Top of dam: | 120 |

Maximum pool design surcharge (SDF stage):	122.1
Recreation pool:	117.3
Spillway crest:	117.2
Streambed at centerline of dam:	100.2
Maximum tailwater:	114.5 (estimate)
d. <u>Reservoir</u>	
Length of maximum pool:	3,700 \pm feet (estimate)
Length of recreation pool:	2,100 \pm feet (estimate)
e. <u>Storage (Acre-feet)</u>	
Recreation pool:	66
Top of dam:	141
f. <u>Reservoir Surface (Acres)</u>	
Top of dam:	32 (estimate)
Recreation pool:	22
Spillway crest:	22
g. <u>Dam</u>	
Type:	Earth fill with concrete spillway.
Length:	327' (effective)
Height:	19.8'
Top width:	35' (average) 28' (minimum)
Side Slopes - Upstream:	Vertical with timber bulkhead.
- Downstream:	2 Horizontal to 1 Vertical
Zoning:	Unknown
Impervious core:	Unknown

Cutoff:	None
Grout curtain:	None
h. <u>Diversion and Regulating Tunnel</u>	
N/A	
i. <u>Spillway</u>	
Type:	Overflow
Length of weir:	23 feet
Crest elevation:	117.2 feet above MSL
Gates:	None
U/S Channel:	Lake Topanemus
D/S Channel:	After the wier, a stepped apron 43 feet-long divided into three channels, before becoming McGellairds Brook.
j. <u>Regulating Outlets</u>	
Low level outlet:	18 inch diameter (inoperable at time of inspection)
Controls:	Manually operated gate valves.
Emergency gate:	N/A
Outlet (mid-level):	12 inch diameter (inoperable at time of inspection)

SECTION 2: ENGINEERING DATA

2.1 Design

No drawings or computations pertaining to original construction of the dam could be found. No data from soil borings, soil tests or other geotechnical data is available. One drawing, dated 1920, and showing details for widening the bridge and spillway is included in the appendices. The drawing was obtained from Monmouth County Engineers Department.

2.2 Construction

Construction history has been provided in Section 1.2.f. Construction of the bridge extension follows the drawing, with the exception that the hand rails have been replaced by traffic barriers. Periodic, unrecorded remedial work has been undertaken by the Township of Freehold to provide road drainage and to restore the road shoulders. It could not be ascertained who had carried out the patching of cracks in the wingwalls.

2.3 Operation

No records of operation of the lake are known to exist.

2.4 Evaluation

a. Availability

The one drawing of the bridge widening was freely available from the County. No other data were available.

b. Adequacy

The engineering data was insufficient to perform even an approximate evaluation of the dam's stability. A preliminary assessment of the dam could be carried out with the data obtained in the field in view of the overall fair condition of the dam.

c. Validity

Information contained in the drawing appeared, by visual inspection, to be correct.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

The visual inspection made of Lake Topanemus Dam revealed that the dam and spillway were in serviceable condition, but that a regular program of inspection and repair is required to maintain its serviceability.

b. Dam

The earth embankment appears to be basically sound. The upstream face, retained by a timber bulkhead, shows very minor local misalignment. The condition of the timber and the tie-bolts is good, with rotting and algae growth being minimal. The downstream face is covered with bushes, trees and low vegetation; its slope is approximately 2H:1V. Local erosion has taken place, notably adjacent to the bridge abutments, mainly due to surface runoff. Seepage from the toe is slight, but at one point 10 feet below the dam crest and towards the left side of the dam, a seepage flow in excess of 5 gpm was found. This seepage appeared to be clean, but silt deposits in the stream created by the seepage indicated that fine material had been washed out from the fill. It is possible that a water main leak is the source of this seepage, and a Township foreman who was present at the inspection stated that a chemical analysis would be made of the leaking water.

Minor settlement was noted on parts of the downstream side of the road, and surface cracks in the road were found. It is not felt that these originated from any general movement of the embankment but rather from the affects of freezing and consolidation. No cracking or sloughing was seen on the downstream face. It was not possible to determine visually if the embankment has been built with a corewall. No evidence of burrowing by animals was found.

Additional sandy fill was being placed by the Township of Freehold during the inspection. The fill, concentrated in the area surrounding the fire hydrant, was end-dumped and spread but not compacted.

The dam appears to be founded on and constructed of Red Bank and Tinton Falls sands. The high silt content of these sands has impeded internal drainage.

c. Appurtenant Structures

1. Spillway

The spillway consists of a vertical concrete wall which acts as a broad-crested weir, supported laterally by the piers and abutments of the bridge carrying Pond Road over the stream. The wall is 9 inches thick and presents a flow length of 23 feet. It is in sound condition with no evidence of erosion, cracking or leakage. The spillway apron steps down to the stream in three horizontal stages and is of concrete construction. Alignment is good and no cracking, spalling or significant erosion was found. Undermining of the apron toe is negligible.

2. Low-Level Outlet

Two circular gate-valve openings were just visible in the central section of the weir and no leaks were noted. The valves are located on the upstream face of the weir; the larger (18") outlet having its invert at the base of the wall, and the smaller (12") at 5 feet higher up. Shafts for the valve-operating keys project above the water surface and have bolted caps. At the inspection, one cap was bolted tight and the other was hanging loosely on one bolt and the shaft had been jammed with cans. The operating key has been lost and thus the outlets are inoperable. An assistant Borough Engineer undertook, at the inspection, to have a key made up and to test the valves.

3. Bridge and Piers

Erosion and spalling of the concrete at the base of the bridge piers and abutments is extensive. In places the piers have been eroded right through. Surface spalling of the concrete is up to 6" deep in small local areas. Between the old and the new construction, joints have opened due to foundation settlement, but this condition appears to have stabilized. The cracks thus formed are no larger than $\frac{1}{4}$ inch across. The piers and abutments have been cut out in two places to allow a water main and a bank of cable conduits to pass through.

The lower bridge stringer is in poor condition, with badly spalled concrete exposing the main reinforcement over most of its length. The remainder of the bridge deck is satisfactory. Stub wingwalls have been provided on the downstream side to retain material adjacent to the abutments. These wingwalls have been partially undermined, and the resulting settlement has caused them to crack away from the abutments. Concrete in the old construction is generally in better condition than in the new.

d. Reservoir Area

The rim of the reservoir is moderately sloped with grass banks

and trees. No indication of instability was apparent. A few residential houses exist on the south bank, and a minor road for recreational users runs along the north bank. Access to the lake is unrestricted and there are a few small boat docks on the shore. Sedimentation at the spillway entrance was about 2 feet deep.

e. Downstream Channel

The downstream channel winds through a broad, wooded valley. The stream banks are steep due to undermining. This has caused trees to fall across the stream and has led to local instability of the embankment near the dam.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

Lake Topanemus Dam is used to impound water for recreation activities. The policy is to maintain a nearly constant lake level close to the elevation of the spillway crest. The lake level is maintained by unregulated discharge over the broad-crested weir in the spillway of the concrete section.

The lake is not lowered on a regular basis, and the last known occasion on which this was done, was in 1961.

4.2 Maintenance of the Dam

There is no program of regular inspection and maintenance of the dam and appurtenant structures. No authority has been identified as being responsible for operation or maintenance and at present, no records of these functions are kept.

4.3 Maintenance of Operating Facilities

The low level outlet gate valves are designed to be operated manually from the bridge. No known maintenance of the valves has been made to keep them operable. The operating key for the valves has been lost and one of the valve shafts is jammed with cans. They are both inoperable at present.

4.4 Evaluation

The present operational procedures are unsatisfactory. The principal cause for concern is that no authority or party has been identified as being responsible for the operation and maintenance of the dam. The general poor level of these functions at present, reflects the lack of responsible supervision.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The drainage area above Lake Topanemus Dam is approximately 1.6 square miles. A drainage map of the watershed of Lake Topanemus damsite is presented on plate 1, Appendix D.

The topography within the basin is generally flat. Elevations range from approximately 200 feet above MSL at the north end of the watershed to about 118 feet at the Lake Topanemus dam site. Land use patterns within the watershed are mostly forest in the north section and urban in the south.

The evaluation of the hydraulic and hydrologic features of Lake Topanemus was based on criteria set forth in the Corps guidelines and additional guidance provided by the Philadelphia District, Corps of Engineers. The SDF for Lake Topanemus Dam falls in a range of $\frac{1}{4}$ PMF to PMF. In this case the low end of the range, $\frac{1}{4}$ PMF, is chosen since the factors used to select size and hazard classification are on the low-side of their respective ranges.

The probable maximum flood (PMF) was calculated from the probable maximum precipitation using Hydrometeorological Report No. 33 with standard reduction factors. Due to the small drainage area, the SCS triangular hydrograph transformed to a curvilinear hydrograph was adopted for developing the unit hydrograph, with the aid of the HEC1-DB Flood Hydrograph Computer program.

Initial and infiltration loss rates, using SCS procedures, were applied to the Probable Maximum Precipitation to obtain rainfall excesses. The rainfall excesses were applied to the unit hydrograph to obtain the PMF and various ratios of PMF utilizing program HEC1-DB.

The SDF peak inflow calculated for Lake Topanemus Dam is 3015 cfs. This value is derived from the $\frac{1}{4}$ PMF hydrograph computed by the HEC1-DB program.

The spillway and overtopping discharge rating curves for Lake Topanemus Dam were combined to form one discharge rating curve. The peak outflow discharge for $\frac{1}{4}$ PMF results in overtopping of the dam.

The stage-outflow relation for the spillway was prepared from

field notes and sketches. The reservoir stage capacity was based on the U.S.G.S. quadrangle topographic maps.

The reservoir storage capacity curve can be computed directly by the conic method, utilizing the HEC1-DB program. The conic method assumes that the reservoir capacity resembles a series of vertically stacked cones. The reservoir surface areas at various elevations were measured by planimeters from topographic maps. Reservoir storage capacity included surcharge levels exceeding the top of the dam, and the spillway rating curve was based on the assumption that the dam remains intact during routing. The spillway rating curve is presented in the hydrologic computations

A breach analysis indicates that the hazard potential for loss of life downstream, due to dam failure from overtopping, is not significantly greater than that which exists without failure.

Drawdown calculations indicate that to empty the lake to an elevation of 108' MSL through the two low-level outlets would take 63 hours, assuming a 2 cfs/square mile inflow. Consequently an increased low-level outlet capacity should be considered.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. However, according to interviews with a member of the staff of the Public Works Department of the Township of Freehold, the dam has never been overtopped.

c. Visual Observation

The valley below the dam is heavily wooded, with much debris, and there are no dwellings immediately downstream of the dam, along McGellairds Brook. The slopes around the lake are moderate and wooded.

d. Overtopping Potential

A storm of magnitude equivalent to the SDF would cause overtopping of the dam to a height of 2.1 feet. Computations indicate that the dam can pass approximately 6% of the PMF without overtopping the dam crest. Since one half the PMF is the minimum Spillway Design Flood (SDF) for this dam, according to the Recommended Guidelines for Safety Inspection of Dams by the Corps of Engineers, the spillway capacity of the Lake Topanemus Dam is assessed as "inadequate."

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There are no signs of major embankment sloughing, local slides or slumps on the downstream side. The top of the upstream side of the embankment is retained by a timber bulkhead which shows no significant sign of deterioration. The remainder was completely under water and was not accessible for visual inspection. The seepages near the abutments and on the left embankment face, described in Section 3.1-b, have not been monitored and no information was uncovered concerning their age or flow rates.

The spillway exhibits no visible evidence of slide failure. Settlement of the newer portion is evidenced by opening of construction joints, but this condition appears to have stabilized. Undermining of the toe of the left abutment has taken place, and stub wingwalls have settled and cracked away from the abutments.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. No embankment or foundation soil parameters are available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in the stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam. The dam has served satisfactorily since its raising before the turn of the century.

d. Post-construction Changes

The original embankment cross-section is not known. An outline of the original bridge and spillway structure is shown in the Plans for widening of the Bridge, dated 1920 (Report Plate 3).

Widening of the road and the bridge/spillway structure is reported to have been completed in 1927, and its present condition concurs with the 1920 plan. Cracks between the stub wingwalls and bridge abutments have been repaired more than once;

it is not known when or by whom these repairs were made.

Since the widening of the road, a set of buried cable conduits have been placed on the upstream side and overhead power cables, supported on pylons, have been installed along the downstream crest. In 1978 a water main was laid in the embankment fill and during the inspection, additional material was being dumped to stabilize a part of the crest against lateral creep.

e. Static Stability

A static stability analysis was not performed for Lake Topanemus Dam because the lack of data on which to base assumptions of material properties and embankment cross-sections might produce misleading results.

The widening of the road and bridge/spillway structure increased the resistance of the dam to lateral thrust. Cracking at the stub wingwalls indicates that they are not stable and this could result in a loss of support for the road adjacent to the abutments. The undermining at the toe of the left abutment has not progressed sufficiently to jeopardize its stability.

Based on a visual inspection which revealed no major misalignment or movement, the static stability of the spillway structure and the embankments of Lake Topanemus Dam is considered satisfactory. However, this can only be confirmed by analyses, based on detailed investigation of constituent soil parameters.

f. Seismic Stability

The dam is located in Seismic Zone 1, as defined in Recommended Guidelines for Safety Inspection of Dams, prepared by the Corps of Engineers. In general, projects located in Seismic Zones 0, 1 and 2 may be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory, and conventional safety margins exist. In this case, the latter conditions are satisfactory, and seismic stability is thus not regarded as a problem.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The dam has been inspected visually and a review has been made of the available engineering data. This assessment is subject to the limitations inherent in the visual inspection procedures stipulated by the Corps of Engineers for a Phase I report.

The safety of Lake Topanemus Dam is in question because the dam does not have adequate spillway capacity to pass the PMF or even one-half of the PMF without overtopping. Overtopping of the dam carries with it the danger of possible progressive failure of the dam or spillway. The dam's present spillway capacity can pass only about 6% of the PMF.

No definitive statement pertaining to the safety of the embankment can be made without acquisition of embankment and foundation material engineering properties and determination of phreatic levels in the downstream part of the embankment. The present embankment, however, has performed adequately since the 1927 modification without failure or evidence of instability. The possibility of minor sloughing may exist, particularly in the event of seismic excitation.

b. Adequacy of Information

The information and data uncovered is not adequate to perform even an approximate evaluation of the dam's stability. The seepage at the toe of the downstream embankment calls for an additional study to determine the actual location of the phreatic surface. Such an investigation will also yield information pertaining to the nature of the material in the embankment. The source of the seepage at the left of the downstream embankment should be determined by chemical analysis.

c. Urgency

Studies to augment the spillway discharge capacity or to determine the hydrologic and hydraulic ability of the dam to withstand overtopping should be undertaken within six months.

Observation wells or piezometers should be installed in the downstream embankment to determine the location of the phreatic surface. The borings should be logged according to the Unified Soil Classification system by qualified personnel and samples

taken to determine the values of pertinent soil parameters. Stability analyses should then be performed in accordance with Chapter 4.4 of the Corps Guidelines. This work should be commenced within 3 months.

A complete topographic survey of the dam area should be made within 3 months, in order to develop a detailed plan and several cross-sections of the dam. The location of utilities on the dam should be shown in the drawings.

The chemical analysis of the seepage from the left of the downstream face should be conducted within one month in order to determine its source. All seepage should be monitored semi-monthly.

7.2 Remedial Measures

a. Alternatives for Increasing Spillway Capacity

Alternatives for increasing spillway capacity are as follows:

1. Increase the dam and bridge height, thus permitting a higher discharge to pass over the spillway and reducing the possibility of overtopping.
2. Lower the weir crest elevation.
3. Widen the weir structure.
4. A combination of any of the above alternatives.

b. Other Remedial Measures

1. The embankment material that has been lost from the downstream face, particularly adjacent to the abutments of the bridge/spillway, should be replaced with quarry-process stone or gravel. Slopes should be reconstructed with keying and compaction of material to improve stability and to support the abutments and wingwalls. This should be undertaken within six months.
2. Concrete slope protection should be provided under road drain outfalls, to reduce erosion, within six months.
3. Restore the areas of eroded and spalled concrete and repair cracks on the spillway and bridge structures with epoxy cement to arrest further deterioration, within six months.
4. Fabricate new operating keys for the low-level outlet valves. Clear the key shafts of debris and provide a lockable device for the shaft caps. This is to be done within six months.

5. All brush and trees should be removed from the downstream slope to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection. This program should be started within 12 months.

c. Recommendations


The following additional action is recommended.

1. Establish ownership of the dam immediately.
2. Establish a flood warning system for the downstream communities within three months.
3. Develop schemes for increasing low-level outlet discharge capacity.


d. O & M Procedures

A formalized program of annual inspection of the dam by an experienced party should be initiated, utilizing the standard visual check list in this report. Headwater and tailwater gages should be installed in the dam, and read out during severe rain storms and at routine operating and maintenance visits to the dam. A permanent log should be kept of all maintenance and operating events of the dam, the lake and the outlet passages.

PLATES



VICINITY MAP





LEGEND


CRETACEOUS

- Kms** Navesink Marl
Dark Green Glauconitic Marl with Shell Bed at the Base.
- Kmw** Mount Laurel and Wenonath Sands
Coarse Glauconitic Sand (Mount Laurel) overlying
Fine Micaceous Sand (Wenonath).
- Krb** Red Bank and Tinton Sands
Coarse Rusty Sand, consolidated in place by Iron
Oxide.
- Contact

GEOLOGIC MAP LAKE TOPANEMUS



Present Work shown ———
Proposed Work shown ———



Cut present wall to the
line to next pier
Cut present wall to the
line to next beam




The image contains three hand-drawn architectural drawings of a bridge structure:

- Plan View (Top):** A top-down view of a bridge deck. It shows a rectangular deck with a central section labeled "A-A". Dimensions include "10' 0\"
- Section A-A (Middle):** A cross-section of the bridge deck. It shows a rectangular deck with a central section labeled "A-A". Dimensions include "10' 0\"
- Section B-B (Bottom):** A cross-section of the bridge deck, showing the internal structure. It includes labels for "CONCRETE" and "STEEL". Dimensions include "10' 0\"

[illegible]

Figure 1 is a schematic diagram of the experimental setup. It shows a reaction vessel with a stirrer and a thermometer. The vessel is connected to a gas inlet and a gas outlet. The gas outlet leads to a gas absorber, which is connected to a gas meter. The reaction vessel is labeled "Reaction vessel" and the gas absorber is labeled "Gas absorber". The gas meter is labeled "Gas meter".

ION ON LINE A-A



APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION, MAINTENANCE DATA

CHECK LIST
VISUAL INSPECTION

PHASE I

Name of Dam Lake Topanemus County Monmouth State New Jersey Coordinators NJDEP

Date(s) Inspection April 30, 1979 Weather Sunny Temperature 50°F
May 24, 1979
June 1, 1979

Pool elevation at Time of Inspection 117.3' M.S.L. Tailwater at time of Inspection 102' M.S.L.

Inspection Personnel:

April 30, 1979

Eugene Koo
Henry King
Chuck Chin

Owner Representative:

Township Foreman

Art Ackerman
Assistant Borough Engineer
51 W. Main Street
Freehold, NJ 07728

May 24, 1979

William Flynn

June 1, 1979

Rhon Ernest-Jones

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
<p>SURFACE CRACKS</p> <p>Isolated minor cracks in the paved surface of the road parallel to the centerline, mainly on downstream side. Timber bulkhead in good condition. Heavy ground covering of leaves and vegetation prevents inspection of downstream face for cracks. Recently placed sandy fill shows cracking due to initial settlement.</p>		<p>No treatment required. Probably due to frost action.</p>
<p>UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE</p> <p>The embankment toe adjacent to the downstream left wingwall has eroded from tailwater vortex action. Some minor cracking is apparent. No cracks or unusual movement noted elsewhere.</p>		<p>Treatment as for erosion.</p>
<p>SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES</p> <p>The downstream face of the embankment is covered with a heavy growth of trees and vegetation. Minor erosion has taken place due to water drainage from the road. Some fine material has been washed out from the embankment material due to minor seepage. No evidence of sloughing.</p>		<p>Continue practice of fill replacement. Clear the downstream face of trees and vegetation. Step or key and compact new fill.</p>
<p>VERTICAL & HORIZONTAL ALIGNMENT OF THE CREST</p> <p>No major misalignment or settlement is visible. Roadway is at or slightly below the top of the bulkhead.</p>		
<p>RIPRAP FAILURES</p> <p>N/A</p>		

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
IMPERVIOUS CORE	No evidence exists of a clay core. The timber bulkhead and the concrete walls retard seepage through the embankment.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	This zone is in poor condition on the downstream face. Loss of material has taken place on both sides from surface water drainage and from seepage. Stub wingwalls have settled as a result, and the main wingwall on the left has been undermined. The slope is reinforced by a well developed root system.	Add quarry process stone or riprap to restore the slope to a stable condition.
ANY NOTICEABLE SEEPAGE	Water was noted seeping at a rate exceeding 5 gpm from a point 10 feet below the dam crest, to the left of the recently placed fill. Other minor seepage was noted over the entire downstream face, and this appeared to have been occurring for many years (evidenced by the accumulation of silt at the toe).	The Township foreman undertook to have the water chemically tested to determine if it was a leak from the water main. This has not been done, and should be pursued further.
STAFF GAGE AND RECORDER	N/A	
DRAINS	Two twelve inch diameter road drains discharge onto the downstream embankment face, and have caused some local erosion.	Restore the eroded material and provide surface protection under drain outfall.

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CONCRETE WEIR	<p>The concrete weir is in good condition with no leakage evident. It is supported laterally by the two sidewalls, two bridge-piers and three concrete counterforts. No horizontal misalignment or evidence of settlement was observed.</p>	<p>Water flow over weir was light at time of inspection, but visibility of weir was poor.</p>
APPROACH CHANNEL	<p>Channel walls have undergone minor erosion at the water surface.</p>	<p>No treatment.</p>
DISCHARGE CHANNEL	<p>The spillway apron steps down in three horizontal stages to the downstream end. No undue surface erosion, cracking or misalignment was noted. No undermining of toe. Debris on apron.</p>	
BRIDGE AND PIERS	<p>The old bridge and discharge channel were extended in 1927. The old part appears to be in better condition than the new extension. Concrete in the new section has been severely eroded at the junction with the apron, in both the side walls and the intermediate piers. Construction joints have cracked and surface spalling up to 6" deep was noted over small areas. Steel rebar is exposed in bridge stringers.</p>	<p>Spalled and eroded concrete areas should be cleaned out and repaired with epoxy grout. Cracks to be grouted.</p>
FOUNDATIONS	<p>Red Bank and Tinton Falls Sand. The type of foundation is not known. Settlement of the extension has stabilized, except for the stub wingwalls which have been patched more than once.</p>	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
<p>CRACKING & SPALLING OF CONCRETE SURFACES IN STILLING BASIN</p> <p>See Discharge Channel and Bridge and Piers Observations.</p>		
<p>INTAKE STRUCTURE</p> <p>None</p>		
<p>OUTLET STRUCTURE</p> <p>See Discharge Channel.</p>		
<p>OUTLET FACILITIES</p> <p>Two circular gate-valve openings just visible in the central section of the concrete weir. Operating key shafts project above water surface and have bolted caps. One shaft was jammed with cans, the top unbolted. The other cap was in place. No leaks noted around valve openings. Valves not operable.</p>		<p>Operating key for gate-valves is missing and whereabouts not traceable. Borough Engineer undertook to have a key made and to test the valves in the near future.</p>
<p>EMERGENCY GATE</p> <p>None.</p>		

INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
MONUMENTATION/SURVEYS None		Install a nearby benchmark.
OBSERVATION WELLS None		
WEIRS None		Install gages to measure lake and tailwater elevations.
PIEZOMETERS None		
OTHERS None		

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SLOPES	Banks are grassed. Slopes to lake are very moderate.	
SEDIMENTATION	Little vegetation. Two foot of silt at spillway entrance.	
USE	Recreation and esthetic purposes only.	
SHORELINE BUILDINGS	A few small-boat landing stages.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CONDITION (OBSERVATIONS, DEBRIS, ETC.)	Fallen trees are visible in the downstream channel. Meandering and undermining of the bank has taken place, leading to instability of banks near the dam. The stream becomes shallow beyond the stilling pool under the apron toe.	
SLOPES	The channel banks are steep.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	None in immediate area of dam, before stream passes under Route 9. Very few inhabitable buildings within one mile downstream of dam.	"High" hazard potential is due to the excessive damage likely to occur to Pond Road and the utilities over the dam, and to the loss of life from Lake and road users.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	None available - to be made up from field observations.
REGIONAL VICINITY MAP	County Map - Monmouth County, U.S.G.S. Quad Sheet-Freehold.
CONSTRUCTION HISTORY	From County and Borough Engineers
TYPICAL SECTIONS OF DAM	From 1920 plan for road widening.
HYDROLOGIC/HYDRAULIC DATA	None available.
OUTLETS - PLAN	None available.
- DETAILS	None available.
- CONSTRAINTS	None available.
- DISCHARGE RATINGS	None available.
RAINFALL/RESERVOIR RECORDS	None available.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
(continued)

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	Rutgers University - Eng. Soil Survey for Monmouth County. Quad sheet overlay.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None available.
POST-CONSTRUCTION SURVEYS OF DAM	None available.
BORROW SOURCES	None available.
SPILLWAY PLAN - SECTIONS - DETAILS	In 1920 Bridge Widening Plans.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
(continued)

ITEM	REMARKS
OPERATING EQUIPMENT PLANS AND DETAILS	None available.
MONITORING SYSTEMS	None.
MODIFICATIONS	Bridge Widening Plans.
HIGH POOL RECORDS	None recorded.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OF FAILURE OF DAM - DESCRIPTION	None reported.
- REPORTS	
MAINTENANCE OPERATION RECORDS	None with Township.

APPENDIX B

PHOTOGRAPHS

(Taken on April 30 and June 1, 1979)

Lake Topanemus Dam




Photo No. 1 - Overall view of dam from upstream. The spillway and bridge structure are in the foreground. Note the key shafts for the low level outlet valves projecting from the water.




Photo No. 2 - View of spillway apron and bridge from downstream.



Photo No. 3 - View of middle outlet channel and spillway. Note the deteriorated concrete at the foot of the bridge pier.



Photo No. 4 - Detail of crack between left bridge abutment and stub wing-wall.

Lake Topanemus Dam




Photo No. 5 - Detail showing the base of bridge pier. Deterioration in this zone is worse in the new section than in the original.



Photo No. 6 - Detail of spalled concrete in the left abutment. Silt-Laden water now seeping through.

Lake Topanemus Dam




Photo No. 7 - Typical view of undergrowth on downstream embankments. Photo shows the point of issue of the worst seepage from the downstream face.



Photo No. 8 - View of downstream embankment face to the right of the spillway. Note the loss of material due to erosion under the road drain outfall.



Photo No. 9 - Detail showing loss of material and seepage around the toe of the left abutment.



Photo No. 10 - Overall view roadway looking to the right. Cracking in the surface of the road appears to be due to freezing.

Lake Topanemus Dam



Photo No. 11 - View of Lake Topanemus looking upstream from the right shore. Note moderate slopes.



Photo No. 12 - View of downstream channel - McGellairds Brook. Note undermining of the banks and the fallen trees.

APPENDIX C

SUMMARY OF ENGINEERING DATA

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

Name of Dam: Lake Topanemus Dam

Drainage Area Characteristics: 1.6 square miles, generally flat, forest, minor residential.

Elevation Top Normal Pool (Storage Capacity): 117.3' MSL (66 acre-feet)

Elevation Top Flood Control Pool (Storage Capacity): N/A

Elevation Maximum Design Pool: 122.1' MSL (SDF pool: 215 acre-feet)

Elevation Top Dam: 120' MSL (141 acre-feet)

SPILLWAY CREST

a. Elevation 117.2' MSL

b. Type Broad-crested weir, subdivided

c. Width 9 inches

d. Length 23 feet

e. Location Spillover Right side of dam.

f. No. and Type of Gates None.

OUTLET WORK

a. Type Open channels (three)

b. Location D/S of weir.

c. Entrance Inverts 117.2' MSL

d. Exit Inverts 104' MSL

e. Emergency Draindown Facilities Two Gate Valves 18" & 12" dia.

HYDROMETEOROLOGICAL GAGES

a. Type None


b. Location None

c. Records None

MAXIMUM NON-DAMAGING DISCHARGE 176 cfs at elevation 120' MSL.

APPENDIX D

HYDROLOGIC COMPUTATIONS



LAKE TOPANEMUS DAM
DRAINAGE BASIN

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT NJ DAM SAFETY INSPECTION GROUP X
LAKE TOPANEMUS
COMPUTED BY BIC CHECKED BY _____

SHEET NO. 1 OF _____
JOB NO. 10-A20-01
DATE 5/15/79

SHE CLASSIFICATION

SURFACE AREA OF MAIN IMPOUNDMENT	22 ACRE ±
AVERAGE DEPTH OF LAKE	8 FT ±
STRUCTURAL HEIGHT OF DAM	19.8 FT
SIZE CLASSIFICATION	SMALL

HAZARD POTENTIAL CLASSIFICATION

RECREATION LAKE WITH HEAVILY TRAVELED ROADS
WHICH IS PART OF IMPOUNDMENT STRUCTURE

HAZARD POTENTIAL CLASSIFICATION	HIGH
---------------------------------	------

RECOMMENDED SDF	$\frac{1}{2}$ PMF
-----------------	-------------------

HYDROLOGIC ANALYSIS

THE HEC-1 DB WILL BE USED TO ROUTE THE
FLOOD USING SCS TRIANGULAR UNIT HYDROGRAPH
WITH CURVILINEAR TRANSFORMATION

D.A. = 1.6 sq mi.

PRECIPITATION

FROM FIG. 15, ZONE G (REF. "DESIGN OF SMALL DAM" 1971)

Probable Max. PRECIPITATION = 26 INCHES FOR 6 HR.

DURATION AND 10 - SQ MI - AREA

DURATION (HRS)	% OF PMP	Values are reduced by 20% to account for misalignment of Basin & Storm isohyets
6	100	
12	109	
24	117	
48	126	

INFILTRATION DATA

DRAINAGE CONSISTS OF MOST OF M-27 ge, M-24 ge, $\frac{AM-20}{M-27}$ ge MATERIAL
(REF. 'ENGINEERING SOIL SURVEY OF NJ - MAMMOUTH COUNTY,
RUTGERS UNIVERSITY)

HYDROLOGIC SOIL GROUP

D + SMALL PORTION B

LAND USED $\frac{1}{3}$ URBAN $\frac{2}{3}$ WOODED LOTS

USE INITIAL INFILTRATION

1.0 INCH

USE CONSTANT MINIMUM RATE

0.08 INCH/HR.

TIME OF CONCENTRATION

1) ESTIMATING T_c FROM VELOCITY ESTIMATE & WATER COURSE LENGTH			
	SLOPE	VEL.	REMARK
OVERLAND FLOW	20/2200	1.0	PASTURE
CHANNEL REACH	$\frac{80}{8000}$	1.5	NEGLECTING FLOW THRU LAKE

$$T_c = \left(\frac{2200}{1} + \frac{8000}{1.5} \right) \frac{1}{3600} = 2.09 \text{ hr.}$$

(REF. SCS' HYDROLOGY HANDBOOK')

- 2) ESTIMATING T_c FROM VELOCITY & WATERCOURSE LENGTH.
ASSUME SAME VELOCITY FOR OVERLAND & CHANNEL FLOW

$$T_c = \frac{10200}{1.5 \times 3600} = 1.89 \text{ hr}$$

- 3) FROM NOMOGRAPH "DESIGN OF SMALL DAM"

$$AH = 150' \quad L = 10200 \text{ ft}$$

$$T_c = 0.95 \text{ Hr.}$$

- 4) KIRPICH

$$T_c = 0.0078 K^{.77} \quad K = \frac{L}{S} \quad S = \frac{H}{L}$$

$$= 1.19 \text{ hr.}$$

TIME OF CONCENTRATION CONTINUED

5) USING THE F.A.A. FORMULA FOR SURFACE FLOW (AIRPORT DRAINAGE)

$$T_C = \frac{1.8 (1.1 C) \sqrt{D}}{\sqrt[3]{S}}$$

$$D = 10200'$$

$$C = 0.35 \text{ (URBAN RESIDENT)}$$

$$S = \frac{100}{10200} = 1\%$$

$$T_C = \frac{1.8 (1.1 - 0.35) \sqrt{10200}}{\sqrt[3]{1} (60)} = 2.29 \text{ hr}$$

6) G.B. WILLIAMS FLOOD COMMITTEE

$$T = 0.908 L \sqrt[5]{\frac{1}{FD}}$$

T IS THE PERIOD IN HOURS

L IS THE LENGTH OF THE CATCHMENT IN MILES

D IS THE DIAMETER IN MILES OF A CIRCLE HAVING THE SAME AREA

F IS THE CATCHMENT SLOPE EXPRESSED AS IN %

$$T = 0.908 \left(\frac{10200}{5280} \right) \sqrt[5]{\frac{1}{1 \times 1.43}} = 1.63 \text{ hr.}$$

$$\text{USE } T_C = 1.89 \text{ hr}$$

$$\text{LAG} = 0.6 T_C = 1.13 \text{ hr}$$

$$\underline{\text{LAG} = 1.13 \text{ hr}}$$

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT LAKE TOPAHEMUS
COMPUTED BY EK

SHEET NO. 5 OF
JOB NO. 10-A20-01
DATE 5/5/79

ELEVATION - AREA - CAPACITY RELATIONSHIP

INFORMATION OBTAINED FROM U.S.G.S.

ELE.	108*	117.3	120	140
SURFACE AREA (AC)	0	22	32	106.5




* BOTTOM OF LAKE AT SPILLWAY

HEC-1 DB PROGRAM WILL DEVELOP STORAGE CAPACITY FROM
SURFACE AREA & ELEVATIONS

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT LAKE TOHAWA
COMPUTED BY EK CHECKED BY _____

SHEET NO. 6 OF _____
JOB NO. 10-A30-01
DATE 5/16/79



FREDERIC R. HARRIS, INC.

CONSULTING ENGINEERS

SUBJECT

Lake Topanemus

SHEET No. 1


OF

JOB No. 10-A20-01

COMPUTED BY E K

CHECKED BY

DATE 5/16/79



Assume C_2 & $C_3 = 2.75$ due to losses caused by bridge railing
(REF. HEC-2 WATER SURFACE PROFILES USER MANUAL, FEB. 1978)
 $C_1 = 2.7$ KING & BREWER pg. 5-46 Table 5-3
 $C_1 = 0.63$


ELE.	H ₁	H ₂	H ₃	L ₁	L ₂	L ₃	C ₁	C ₂	C ₃	$Q = C_1 L_1 H_1^{1.5} + C_2 L_2 H_2^{1.5} + C_3 L_3 H_3^{1.5}$ $C_1 L_1 H_1^{1.5}$ UP TO $H_1 = 1'$ FOR $H_1 > 1'$ USE ORIFICE EQ FOR SECTION 1 $Q = \frac{2}{3} 1.48 C_d (H_1^{1.5} - H_2^{1.5}) + C_2 L_2 H_2^{1.5} + C_3 L_3 H_3^{1.5}$
117.2										
118.2				23	0	0	2.7			$62 + 0 + 0 = 62 \text{ cfs}$
120				23	0	0	C ₁ 0.63			$176 + 0 + 0 = 176$
120.5			0.5	23	210	0	0.63	2.75		$194 + 263 + 0 = 457$
121.0			0.4	23	210	57	0.63	2.75	2.75	$211 + 743 + 40 = 954$
121.5			0.9	23	270	57	0.63	2.75	2.75	$227 + 1264 + 134 = 1731$
122.0			1.4	23	270	57	0.63	2.75	2.75	$241 + 2160 + 260 = 2601$
124			3.4	23	270	57	0.63	2.75	2.75	$292 + 5940 + 993 = 7215$
126			5.4	23	270	57	0.63	2.75	2.75	$335 + 10912 + 1967 = 13214$
128			7.4	23	270	57	0.63	2.75	2.75	$373 + 16801 + 3155 = 20329$

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT WYDAM INSPECTION GROUP X
LAKE TOPANEFANUS

COMPUTED BY JEK CHECKED BY _____

SHEET NO. 5 OF _____
JOB NO. 10-A20-01
DATE _____




FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT _____
LAKE TOPANMUS
COMPUTED BY E.K. _____

SHEET NO. 9 OF _____
JOB NO. 0420-01
DATE _____

OVERTOPPING POTENTIAL



OVERTOPPING OF DAM OCCURS AT ELEV. 120 WITH
 $Q = 176 \text{ CFS}$ ($\sim 6\% \text{ PMF}$)

FREDERIC R. HARRIS, INC.

CONSULTING ENGINEERS

SUBJECT

LAKE TOPANEMUS

COMPUTED BY B.K.

CHECKED BY


SHEET NO. 10 OF

JOB NO. 10-A30-01

DATE


BREACH ANALYSIS

ASSUME BREACH BEGINS TO DEVELOP WHEN RESERVOIR STAGE
REACHES ELE. 121.4 (1.4 FT HIGHER THAN THE TOP OF DAM)



FULLY DEVELOPED BREACH

ASSUME BRIDGE ACROSS THE STREAM FAILS INSTANTLY UPON
IMPACT OF THE FLOOD WAVE.



FREDERIC R. HARRIS, INC.

CONSULTING ENGINEERS

SUBJECT

Lake TEPANEMUS

COMPUTED BY

EK

CHECKED BY

SHEET NO.


11

OF

JOB NO.

12-A-20-01

DATE



CROSS - SECTION


END OF REACH 1 (STA. 1.0)

$$S = 0.001$$

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT LAKE TOPANEMUS (REVISED)
COMPUTED BY E. K. CHECKED BY _____

SHEET NO. 12 OF _____
JOB NO. 10-A20-01
DATE AUGUST 1979



FREDERIC R. HARRIS, INC.

CONSULTING ENGINEERS

SUBJECT

LAKE TONAWANDA

COMPUTED BY

RK

CHECKED BY

SHEET NO.

13

OF


JOB NO.

10-A20-01

DATE

8/8/73

DRAWDOWN TIME COMPUTATION



NORMAL ELW TO Start 117.2

DRAINAGE AREA = 1.6 mi²

TW ELW EL. 103.0

Inflow = @ 2 cfs/s.m = 3.2 cfs

Res Area Elev Acres	Ave Area Acres	Volume Ac Ft	Ave Res Elev.	Q Ave outlet Discharge cfs	E, hrs Time to drawdown $\frac{Vol \times 24}{1.48 \times Q}$	Cum time hrs 2.0 csm 2.3 x 1 Q.	Time to drawdown hrs	Cum time hrs
117.2 22								
	20.6	24.7	116.6	35.3	8.48	8.48	0.76	9.2
116 19.1								
	17.9	17.9	115.5	32.2	6.74	15.22	0.67	16.7
115 16.7								
	15.6	15.6	114.5	28.5	6.63	21.85	0.75	24.0
114 14.4								
	13.2	13.2	113.5	24.10	6.64	28.49	0.88	31.55
113 12								
	10.8	10.8	112.5	18.8	6.96	35.45	1.12	39.6
112 9.6								
	8.4	8.4	111.5	16.5	6.17	42.62	1.20	47.8
111 7.2								
	6.0	6.0	110.5	13.8	5.27	47.89	1.22	54.5
110 4.8								
	3.6	3.6	109.5	10.7	4.08	51.97	1.22	59.6
109 2.4								
	1.2	1.2	108.5	~ 6.2	2.35	54.11	1.21	63.1
108 0								

A) TIME OF COMPLETE DRAWDOWN WITH NO INFLOW = 54.1 hrs

B) TIME OF COMPLETE DRAWDOWN WITH 2 cfs or 3.2 cfs = 63.1 hr

(Assume that the surface area of Reservoir varies linearly from 22 acres @ Elev 117.2 to 0 acres @ Elev 108)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

HEC1-DB

COMPUTER PRINT-OUT

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 10

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAN SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 79/08/02.
 TIME 22.57.07.

N J DAN SAFETY INSPECTIONS PROGRAM--GROUP X
 N J 00219 LAKE TO PANEMUS, MONMOUTH COUNTY, NJ
 MULTI-RATIO-PMF ROUTING-F. N. HARRIS INC, WOODBRIDGE, NJ

JOB SPECIFICATION									
NO	NHR	NMIN	IDAY	JHR	IMIN	METG	IPLT	IPRT	NSTAN
150	0	10	0	0	0	0	0	3	0
	JOPER	NWT	LROPT	TRACE					
	5	0	0	0					

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 5 LRATIO= 1

RTIOS= .50 .40 .30 .20 .10

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH THROUGH LAKE TOPANEMUS

ISTAD	ICOMP	IECON	ITAFE	JPLT	JFRT	INANE	ISTAGE	IAUTO
LAKE	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IHYDG	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	2	1.60	0.00	1.60	.80	0.000	0	1	0

PRECIP DATA

SPFE	PHS	K6	R12	K24	R48	R72	R96
0.00	26.00	100.00	109.00	117.00	0.00	0.00	0.00

LOSS DATA

LROPT	STRKR	DLTKR	RTIOL	ERAIN	STKRS	RTIOK	STRIL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.08	0.00	0.00

UNIT HYDROGRAPH DATA

TC= 0.00 LAG= 1.13

RECESSION DATA

STRIO= -1.00 GRCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH-34- END-OF-PERIOD ORDINATES, TC= 0.00 HOURS, LAG= 1.13 VOL= 1.00

36.	106.	210.	359.	508.	601.	634.	630.	576.	510.
424.	326.	255.	203.	164.	132.	106.	84.	67.	54.
43.	34.	27.	22.	18.	14.	11.	9.	7.	6.
5.	4.	3.	2.	1.	0.				

FFIF INFLOW HYDROGRAPH

MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PI COMP Q
1.01	10	1	.02	0.00	.02	1.
1.01	20	2	.02	0.00	.02	1.
1.01	30	3	.02	0.00	.02	1.
1.01	40	4	.02	0.00	.02	1.
1.01	50	5	.02	0.00	.02	1.
1.01	1.00	6	.02	0.00	.02	1.
1.01	1.10	7	.02	0.00	.02	1.
1.01	1.20	8	.02	0.00	.02	1.
1.01	1.30	9	.02	0.00	.02	1.
1.01	1.40	10	.02	0.00	.02	1.
1.01	1.50	11	.02	0.00	.02	1.
1.01	2.00	12	.02	0.00	.02	1.
1.01	2.10	13	.02	0.00	.02	1.
1.01	2.20	14	.02	0.00	.02	1.
1.01	2.30	15	.02	0.00	.02	1.
1.01	2.40	16	.02	0.00	.02	1.
1.01	2.50	17	.02	0.00	.02	0.
1.01	3.00	18	.02	0.00	.02	0.
1.01	3.10	19	.02	0.00	.02	0.
1.01	3.20	20	.02	0.00	.02	0.
1.01	3.30	21	.02	0.00	.02	0.
1.01	3.40	22	.02	0.00	.02	0.
1.01	3.50	23	.02	0.00	.02	0.
1.01	4.00	24	.02	0.00	.02	0.
1.01	4.10	25	.02	0.00	.02	0.
1.01	4.20	26	.02	0.00	.02	0.
1.01	4.30	27	.02	0.00	.02	0.
1.01	4.40	28	.02	0.00	.02	0.
1.01	4.50	29	.02	0.00	.02	0.
1.01	5.00	30	.02	0.00	.02	0.
1.01	5.10	31	.02	0.00	.02	0.
1.01	5.20	32	.02	0.00	.02	0.
1.01	5.30	33	.02	0.00	.02	0.
1.01	5.40	34	.02	0.00	.02	0.
1.01	5.50	35	.02	0.00	.02	0.
1.01	6.00	36	.02	0.00	.02	0.
1.01	6.10	37	.05	0.00	.05	0.
1.01	6.20	38	.05	0.00	.05	0.
1.01	6.30	39	.05	0.00	.05	0.
1.01	6.40	40	.05	0.00	.05	0.
1.01	6.50	41	.05	0.00	.05	0.
1.01	7.00	42	.05	0.00	.05	0.
1.01	7.10	43	.05	.02	.03	1.
1.01	7.20	44	.05	.04	.01	4.
1.01	7.30	45	.05	.04	.01	10.
1.01	7.40	46	.05	.04	.01	22.
1.01	7.50	47	.05	.04	.01	39.
1.01	8.00	48	.05	.04	.01	60.
1.01	8.10	49	.05	.04	.01	84.
1.01	8.20	50	.05	.04	.01	109.
1.01	8.30	51	.05	.04	.01	132.
1.01	8.40	52	.05	.04	.01	153.
1.01	8.50	53	.05	.04	.01	171.
1.01	9.00	54	.05	.04	.01	185.
1.01	9.10	55	.05	.04	.01	196.
1.01	9.20	56	.05	.04	.01	205.
1.01	9.30	57	.05	.04	.01	212.
1.01	9.40	58	.05	.04	.01	217.
1.01	9.50	59	.05	.04	.01	222.
1.01	10.00	60	.05	.04	.01	225.
1.01	10.10	61	.05	.04	.01	228.
1.01	10.20	62	.05	.04	.01	231.
1.01	10.30	63	.05	.04	.01	232.
1.01	10.40	64	.05	.04	.01	234.
1.01	10.50	65	.05	.04	.01	235.
1.01	11.00	66	.05	.04	.01	236.
1.01	11.10	67	.05	.04	.01	237.
1.01	11.20	68	.05	.04	.01	237.
1.01	11.30	69	.05	.04	.01	238.
1.01	11.40	70	.05	.04	.01	238.
1.01	11.50	71	.05	.04	.01	238.
1.01	12.00	72	.05	.04	.01	239.
1.01	12.10	73	.35	.33	.01	249.
1.01	12.20	74	.35	.33	.01	281.
1.01	12.30	75	.35	.33	.01	343.

PMF INFLOW HYDROGRAPH

PERIOD FLOW

MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
1.01	12.40	76	.35	.33	.01	449.
1.01	12.50	77	.35	.33	.01	599.
1.01	13.00	78	.35	.33	.01	776.
1.01	13.10	79	.42	.40	.01	965.
1.01	13.20	80	.42	.40	.01	1158.
1.01	13.30	81	.42	.40	.01	1342.
1.01	13.40	82	.42	.40	.01	1517.
1.01	13.50	83	.42	.40	.01	1678.
1.01	14.00	84	.42	.40	.01	1815.
1.01	14.10	85	.52	.51	.01	1938.
1.01	14.20	86	.52	.51	.01	2052.
1.01	14.30	87	.52	.51	.01	2162.
1.01	14.40	88	.52	.51	.01	2274.
1.01	14.50	89	.52	.51	.01	2388.
1.01	15.00	90	.52	.51	.01	2498.
1.01	15.10	91	.47	.46	.01	2599.
1.01	15.20	92	.79	.78	.01	2701.
1.01	15.30	93	1.42	1.41	.01	2832.
1.01	15.40	94	3.56	3.54	.01	3097.
1.01	15.50	95	1.03	1.01	.01	3516.
1.01	16.00	96	.63	.62	.01	4087.
1.01	16.10	97	.49	.47	.01	4794.
1.01	16.20	98	.49	.47	.01	5454.
1.01	16.30	99	.49	.47	.01	5875.
1.01	16.40	100	.49	.47	.01	6030.
1.01	16.50	101	.49	.47	.01	5979.
1.01	17.00	102	.49	.47	.01	5729.
1.01	17.10	103	.38	.37	.01	5384.
1.01	17.20	104	.38	.37	.01	4954.
1.01	17.30	105	.38	.37	.01	4492.
1.01	17.40	106	.38	.37	.01	4110.
1.01	17.50	107	.38	.37	.01	3799.
1.01	18.00	108	.38	.37	.01	3542.
1.01	18.10	109	.03	.01	.01	3306.
1.01	18.20	110	.03	.01	.01	3073.
1.01	18.30	111	.03	.01	.01	2834.
1.01	18.40	112	.03	.01	.01	2570.
1.01	18.50	113	.03	.01	.01	2280.
1.01	19.00	114	.03	.01	.01	1980.
1.01	19.10	115	.03	.01	.01	1686.
1.01	19.20	116	.03	.01	.01	1409.
1.01	19.30	117	.03	.01	.01	1161.
1.01	19.40	118	.03	.01	.01	946.
1.01	19.50	119	.03	.01	.01	767.
1.01	20.00	120	.03	.01	.01	629.
1.01	20.10	121	.03	.01	.01	521.
1.01	20.20	122	.03	.01	.01	435.
1.01	20.30	123	.03	.01	.01	366.
1.01	20.40	124	.03	.01	.01	311.
1.01	20.50	125	.03	.01	.01	285.
1.01	21.00	126	.03	.01	.01	266.
1.01	21.10	127	.03	.01	.01	248.
1.01	21.20	128	.03	.01	.01	232.
1.01	21.30	129	.03	.01	.01	216.
1.01	21.40	130	.03	.01	.01	202.
1.01	21.50	131	.03	.01	.01	188.
1.01	22.00	132	.03	.01	.01	176.
1.01	22.10	133	.03	.01	.01	164.
1.01	22.20	134	.03	.01	.01	153.
1.01	22.30	135	.03	.01	.01	143.
1.01	22.40	136	.03	.01	.01	133.
1.01	22.50	137	.03	.01	.01	124.
1.01	23.00	138	.03	.01	.01	116.
1.01	23.10	139	.03	.01	.01	108.
1.01	23.20	140	.03	.01	.01	101.
1.01	23.30	141	.03	.01	.01	94.
1.01	23.40	142	.03	.01	.01	90.
1.01	23.50	143	.03	.01	.01	89.
1.02	0.00	144	.03	.01	.01	89.
1.02	.10	145	0.00	0.00	0.00	89.
1.02	.20	146	0.00	0.00	0.00	87.
1.02	.30	147	0.00	0.00	0.00	84.
1.02	.40	148	0.00	0.00	0.00	79.
1.02	.50	149	0.00	0.00	0.00	74.
1.02	1.00	150	0.00	0.00	0.00	69.

SUM 24.34 21.98 2.35 136517.
(618.) (558.) (60.) (3865.73)

HYDROGRAPH ROUTING

ROUTING DISCHARGE THROUGH LAKE TOPANEMUS

DAM DATA		
TOPEL	COQU	EXPD DAMWID
120.0	0.0	0.0
		0.

STATION DAM, PLAN 1, RATIO 1 (1/2 P.M.F.)

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW									
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
7.	10.	12.	15.	18.	21.	24.	27.	30.	33.
36.	39.	41.	44.	46.	49.	51.	54.	56.	58.
60.	62.	64.	66.	69.	74.	80.	88.	99.	113.
128.	145.	164.	231.	381.	543.	715.	846.	952.	1078.
1169.	1242.	1308.	1388.	1510.	1690.	1950.	2251.	2535.	2782.
2912.	2921.	2837.	2687.	2513.	2336.	2160.	2000.	1857.	1727.
1612.	1492.	1363.	1224.	1080.	941.	842.	737.	634.	537.
454.	409.	365.	324.	287.	255.	228.	205.	185.	175.
173.	171.	169.	166.	164.	161.	158.	156.	153.	150.
147.	144.	141.	139.	136.	133.	131.	128.	125.	123.
STORAGE									
66.	66.	66.	66.	66.	66.	66.	66.	66.	66.
66.	66.	66.	66.	66.	66.	66.	66.	66.	66.
66.	66.	66.	66.	66.	66.	66.	66.	66.	66.
66.	66.	66.	66.	66.	66.	66.	66.	66.	66.
69.	69.	70.	71.	72.	74.	75.	76.	77.	78.
79.	80.	81.	82.	83.	84.	85.	86.	87.	88.
89.	89.	90.	91.	92.	94.	97.	100.	105.	111.
118.	126.	135.	144.	153.	160.	166.	170.	174.	177.
179.	180.	182.	184.	187.	191.	196.	203.	209.	213.
215.	215.	214.	212.	208.	204.	201.	197.	194.	192.
189.	186.	183.	180.	177.	174.	170.	167.	163.	160.
157.	154.	152.	149.	147.	145.	144.	142.	141.	140.
139.	138.	137.	136.	134.	133.	132.	131.	129.	128.
127.	125.	124.	123.	121.	120.	119.	118.	116.	115.
STAGE									
117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2
117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2
117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2
117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2	117.2
117.3	117.4	117.4	117.4	117.5	117.5	117.6	117.6	117.7	117.7
117.8	117.8	117.9	117.9	118.0	118.0	118.1	118.1	118.1	118.1
118.2	118.2	118.2	118.3	118.3	118.4	118.5	118.6	118.8	119.0
119.2	119.5	119.8	120.1	120.4	120.6	120.8	120.9	121.0	121.1
121.1	121.2	121.2	121.3	121.4	121.5	121.6	121.8	122.0	122.1
122.1	122.1	122.1	122.1	122.0	121.9	121.8	121.7	121.6	121.5
121.4	121.3	121.3	121.2	121.1	121.0	120.9	120.8	120.7	120.6
120.5	120.4	120.3	120.3	120.2	120.1	120.1	120.1	120.0	120.0
120.0	119.9	119.9	119.8	119.8	119.8	119.7	119.7	119.6	119.6
119.5	119.5	119.5	119.4	119.4	119.3	119.3	119.2	119.2	119.2

PEAK OUTFLOW IS 2921. AT TIME 17.00 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5
 .50 .40 .30 .20 .10

HYDROGRAPH AT LAKE 1.60 1 3015. 2412. 1809. 1206. 603.
 (4.14) (85.37) (68.30) (51.22) (34.15) (17.07) (

ROUTED TO DAM 1.60 1 2921. 2319. 1728. 1121. 389.
 (4.14) (82.71) (65.66) (48.95) (31.75) (11.03) (

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 INITIAL VALUE SPILLWAY CREST TOP OF DAM
 117.20 117.20 120.00
 66. 141.
 0. 176.

RATIO OF PMF	MAXIMUM RESERVOIR W. S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
50	122.14	2.14	215.	2921.	7.67	17.00	0.00
40	121.84	1.84	204.	2319.	7.00	17.00	0.00
30	121.50	1.50	192.	1728.	6.17	17.00	0.00
20	121.11	1.11	178.	1121.	5.00	17.00	0.00
10	120.38	.38	153.	389.	2.83	17.83	0.00

A1 M J DAM SAFETY INSPECTIONS PROGRAM---GROUP X
A2 M-J 00219 LAKE TO PANENUS, MONMOUTH COUNTY, NJ
A3 MUILT RATIO PMF ROUTING, F. R. HARRIS INC, WOODBRIDGE, NJ

B	150	0	10	0	0	0	0	5				
J	5											
J	2	1	1									
J1	0.5											
K	0	LAKE			0	0	1					
K1												
M	1	2	1.6		1.6	0.8					1	
P	0	26	100	.109	117							
T							1.0	0.08				
W2		1.13										
X	-1	-0.05	2									
K	1	DAM			0	0	1					
K1												
Y												
Y1	1						-117.2	-1				
Y4	117.2	118.2	120	120.5	121	121.5	122	124	126	128		
Y5	0	42	176	457	954	1731	2601	7215	13214	20329		
Y6	0	22	32	106.5								
Y8	108	117.3	120	140								
Y8	117.2											
YD	120											
YB	30	1	109	1	117.2	121.40						
YB	30	1	109	1.0	117.2	200.00						
K	1	1.0										
K1	D/S LOC 10+00											
Y												
Y1	1						-1					
Y6	0.1	0.05	0.1	102	160	1000	0.001					
Y7	200	160	450	140	700	120	750	102	770	102		
Y7	850	120	1250	140	3100	160						
K	1	4.2										
K1	D/S LOC 42+00											
Y												
Y1	1						-1					
Y6	0.1	0.05	0.1	100	140	3200	0.00043					
Y7	500	160	800	140	1000	120	1220	100	1320	100		
Y7	1600	120	2200	140	2300	140						
K	1	8.0										
K1	D/S LOC 80+00											
Y												
Y1	1						-1					
Y6	0.1	0.05	0.1	93	120	3800	0.0018					
Y7	2000	140	2200	120	2550	100	2770	93	2900	93		
Y7	2950	100	3650	120	4300	120						
K	1	11.6										
K1	D/S LOC 116+00											
Y												
Y1	1						-1					
Y6	0.1	0.05	0.1	86	100	3600	0.0019					
Y7	1400	105	2000	100	3100	100	3800	86	4000	86		
Y7	4350	95	7100	100	7500	100						
K	1	15.9										
K1	D/S LOC 159+00 NR OLD TENNENT CHURCH											
Y												
Y1	1						-1					
Y6	0.1	0.05	0.1	79	120	4300	0.0016					
Y7	700	125	1000	120	1200	100	1850	79	2050	79		
Y7	2750	80	4050	100	4550	120						
K	1	190										
K1	D/S LOC 190+00 AT TAYLOR MILLS											
Y												
Y1	1						-1					
Y6	0.15	0.05	0.1	72	85	3100	0.0023					
Y7	1500	85	2600	80	3700	80	3850	72	3950	72		
Y7	4050	80	5200	80	7000	100						
K	99											

180VFS

STATION DAM

TIME (HRS)	(D) INTERPOLATED BREACH HYDROGRAPH					(E) POINTS AT NORMAL TIME INTERVAL				
	1400.	2000.	2400.	2800.	3200.	3600.	4000.	4400.	4800.	0.
16.00 1.	*									0.
16.02 2.	0	B								0.
16.04 3.		0	B							0.
16.06 4.		0	B							0.
16.08 5.		0	B							0.
16.10 6.		0	B							0.
16.13 7.		0	B							0.
16.15 8.		0	B							0.
16.17 9.		0	B							0.
16.19 10.		0	B							0.
16.21 11.		0	B							0.
16.23 12.		0	B							0.
16.25 13.		0	B							0.
16.27 14.		0	B							0.
16.29 15.		0	B							0.
16.31 16.		0	B							0.
16.33 17.		0	B							0.
16.35 18.		0	B							0.
16.37 19.		0	B							0.
16.40 20.		0	B							0.
16.42 21.		0	B							0.
16.44 22.		0	B							0.
16.46 23.		0	B							0.
16.48 24.		0	B							0.
16.50 25.		0	B							0.
16.52 26.		0	B							0.
16.54 27.		0	B							0.
16.56 28.		0	B							0.
16.58 29.		0	B							0.
16.60 30.		0	B							0.
16.62 31.		0	B							0.
16.65 32.		0	B							0.
16.67 33.		0	B							0.
16.69 34.		0	B							0.
16.71 35.		0	B							0.
16.73 36.		0	B							0.
16.75 37.		0	B							0.
16.77 38.		0	B							0.
16.79 39.		0	B							0.
16.81 40.		0	B							0.
16.83 41.		0	B							0.
16.85 42.		0	B							0.
16.87 43.		0	B							0.
16.90 44.		0	B							0.
16.92 45.		0	B							0.
16.94 46.		0	B							0.
16.96 47.		0	B							0.
16.98 48.		0	B							0.
17.00 49.		0	B							0.

N J DAM SAFETY INSPECTIONS PROGRAM---GROUP X
 N J 00219 LAKE TO PANEMUS, MONMOUTH COUNTY, NJ
 MULTI RATIO PMF ROUTING, F. R. HARRIS INC, WOODBRIDGE, NJ

JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
150	0	10	0	0	0	0	0	5	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

SURFACE AREA= 0. 22. 32. 107.

CAPACITY= 0. 48. 141. 1453.

ELEVATION= 108. 117. 120. 140.

CREL	SPWID	COBW	EXPW	ELEV	COQL	CAREA	EXPL
117.2	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA

TOPEL	COOD	EXPD	DAMWID
120.0	0.0	0.0	0.

DAM BREACH DATA

BRWID	Z	ELBM	TFAIL	WSEL	FAILEL
30.	1.00	109.00	1.00	117.20	121.40

BEGIN DAM FAILURE AT 16.00 HOURS

PEAK OUTFLOW IS 4597. AT TIME 17.00 HOURS

DAM BREACH DATA

BRWID	Z	ELBM	TFAIL	WSEL	FAILEL
30.	1.00	109.00	1.00	117.20	200.00

PEAK OUTFLOW IS 2921. AT TIME 17.00 HOURS

NORMAL DEPTH CHANNEL ROUTING

STA. 1.0 REACH 1

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
1000	0500	1000	102.0	160.0	1000.	00100

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC

200.00	160.00	450.00	140.00	700.00	120.00	750.00	102.00	770.00	102.00
850.00	120.00	1250.00	140.00	3100.00	160.00				

NORMAL DEPTH CHANNEL ROUTING

STA. 4.2

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
1000	0500	1000	100.0	140.0	3200.	00063

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC

500.00	160.00	800.00	140.00	1000.00	120.00	1220.00	100.00	1320.00	100.00
1600.00	120.00	2200.00	140.00	2300.00	140.00				

NORMAL DEPTH CHANNEL ROUTING

STA. 8.0

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
1000	0500	1000	93.0	120.0	3800.	00180

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC

2000.00	140.00	2200.00	120.00	2550.00	100.00	2770.00	93.00	2900.00	93.00
2950.00	100.00	3650.00	120.00	4300.00	120.00				

NORMAL DEPTH CHANNEL ROUTING

Sta. 11.6

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
1000	0500	1000	86.0	100.0	3600.	00190

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
 1400.00 105.00 2000.00 100.00 3100.00 100.00 3800.00 86.00
 4350.00 95.00 7100.00 100.00 7500.00 100.00

NORMAL DEPTH CHANNEL ROUTING

STA. 15.9

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
.1000	.0500	.1000	79.0	120.0	4300.	.00160

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
 700.00 125.00 1000.00 120.00 1200.00 100.00 1850.00 79.00
 2750.00 80.00 4050.00 100.00 4550.00 120.00

NORMAL DEPTH CHANNEL ROUTING

STA. 190

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
.1500	.0500	.1000	72.0	85.0	3100.	.00230

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
 1500.00 85.00 2600.00 80.00 3700.00 80.00 3850.00 72.00
 4050.00 80.00 5200.00 80.00 7000.00 100.00

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION STATION AREA PLAN RATIO 1
 50

HYDROGRAPH AT LAKE 1.60 1 3015.
 (4.14) (85.37)(
 2 3015.
 (85.37)(

ROUTED TO DAM 1.60 1 4597.
 (4.14) (130.18)(
 2 2921.
 (82.71)(

ROUTED TO 1.0 1.60 1 4471.
 (4.14) (126.60)(
 2 2924.
 (82.81)(

ROUTED TO 4.2 1.60 1 4026.
 (4.14) (114.01)(
 2 2773.
 (78.52)(

ROUTED TO 8.0 1.60 1 3816.
 (4.14) (108.05)(
 2 2667.
 (75.53)(

ROUTED TO 11.0 1.60 1 3595.
 (4.14) (101.80)(
 2 2557.
 (72.40)(

ROUTED TO 15.9 1.60 1 3103.
 (4.14) (87.88)(
 2 2267.
 (64.18)(

ROUTED TO 190 1.60 1 3052.
 (4.14) (86.41)(
 2 2247.
 (63.62)(

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
		117.20	117.20	120.00
	ELEVATION STORAGE	66.	66.	141.
	OUTFLOW	0.	0.	176.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	1.52	192.	4597.	3.17	17.00	16.00

PLAN 2		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
		117.20	117.20	120.00
	ELEVATION STORAGE	66.	66.	141.
	OUTFLOW	0.	0.	176.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	2.14	215.	2921.	7.67	17.00	0.00

PLAN 1 STATION 1.0 REACH 1

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	4471.	117.2	17.00

PLAN 2 STATION 1.0

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	2924.	114.6	17.00

PLAN 1 STATION 4.2

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	4026.	108.4	17.33

PLAN 2 STATION 4.2

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	2773.	106.9	17.33

PLAN 1 STATION 8.0

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	3816.	98.3	17.50

PLAN 2 STATION 8.0

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	2667.	97.5	17.67

PLAN 1 STATION 11.6

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	3595.	99.9	17.83

PLAN 2 STATION 11.6

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	2557.	89.2	18.00

PLAN 1 STATION 15.9

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	3103.	81.2	18.50

PLAN 2 STATION 15.9

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	2267.	80.7	18.67

PLAN 1 STATION 190

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	3052.	77.1	18.67

PLAN 2 STATION 190

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50			